

The CN70 ships with a partially charged battery. You can use a DX1, DX2, or DX4 multi-dock and a power supply to charge the battery. You can also charge the battery by connecting the computer directly to an external power supply. Charging options are sold and shipped separately. To order these charging accessories, contact your local Intermec representative.

El modelo CN70 se envía con una batería parcialmente cargada. Necesitará un multi-acoplador DX1, DX2 ó DX4 y una fuente de alimentación para cargarla. También puede cargar la batería conectando el ordenador directamente a una fuente de alimentación externa. Opciones de carga se venden y piden por separado. Para recibir asistencia, contacte a su representante de ventas de Intermec.

Where to Find More Information
Dónde encontrar más información

www.intermec.com
In the U.S.A and Canada, call
1.800.755.5505



Caution: See Compliance Insert for use restrictions associated with this product.
Precaución: Consulte el Inserto de cumplimiento para ver las restricciones de uso asociadas con este producto.

This product is protected by one or more patents. Este producto esta protegido por una o varias patentes.

Electrical rating. Calificación eléctrica: $\approx$ 4,37 / 4,8 V; 2 / 1,5 A

CN70 Mobile Computer Quick Start Guide



P/N 930-258-002



Worldwide Headquarters
6001 36th Avenue West
Everett, Washington 98203
U.S.A.

tel 425.348.2600

fax 425.355.9551

www.intermec.com

© 2012 Intermec Technologies Corporation. All rights reserved.



CN70

Mobile Computer

1000CP03C, 1000CP03S



Quick Start Guide

Guía de comienzo rápido para la computadora móvil

CN70

